Call E-010	9051980			©2002 Fujitsu Services Limited
	Closed Sciences Wed 05 Septe	mber 2001 23:17		153405
6.0	3 B Thu 06 Septer	mber 2001 18:17		PATHWAY
	Posts 0			uk081199 / SMC1
		Caller Details GRO		
			j	153405
11	Ann-Marie Collin - SMC			
Francis I vo	George H	Call Problem Details	::: HD15	
		Call Closure Details		
06/	09/2001 18:17		R01	RS10
Cal	l Close by Rebecca Aloneftis: changed gateway processor du	ue to software error. Call closure code of failure a	and repair code 821	-
		Call Asset Details		
			Sec. (Circle)	
	PATICLX365/400B			entre de la companya
		Call Activity Log		
OPEN	05 September 2001 23:14 by gb083797 / SMC1 New call taken by Ann-Marie Collin: NT ctitical event receive	ed on 5.9.01 @ 23.01. The evice \Device\Harddisk	Saved: 05 September 2001 23: 0\Partition1, has a had block Kel re	
Information	05 September 2001 23:20 by gb083797 / SMC1	10 01 0.0.0 1 @ 20.0 1. The evice, is evice in land disk	Saved: 05 September 2001 23:	
	Please contact PM and obtain access times to swap out gat	eway counter.		
REASSIGN	05 September 2001 23:21 by gb083797 / SMC1	Croup SMC1 to Croup SMC1	Saved: 05 September 2001 23:	21
MODIFY	Call # E-0109051980 was Reassigned from Ann-Marie Collin 05 September 2001 23:21 by gb083797 / SMC1	r, Group SMC I to Group SMC I	Saved: 05 September 2001 23:	21
	Call information modified by Ann-Marie Collin CSR ID: from 'g	b083797' Product ID: from 'Unknown Product' to 'F		
DULL IN DE ACCION	to 'PT03'		0	44
BULK REASSIGI	v 06 September 2001 07:41 by uk066602 / SMC1 Call: E-0109051980 was BULK REASSIGNED from Group= SI	MC1 to CSR= uk081232. Group= SMC1	Saved: 06 September 2001 07:	41
Contacted	06 September 2001 08:58 by uk081232 / SMC1	, , , , , ,	Saved: 06 September 2001 08:	58
	Contacted Pm for access times but there was no answer. Is	will call back later.		
REASSIGN	06 September 2001 09:45 by gb053549 / HSH1 Call # E-0109051980 was Reassigned from Sheron Palmer, 0	Proug SMC1 to Stoyon College Group USU1	Saved: 06 September 2001 09:	46
Information	06 September 2001 09:46 by gb053549 / HSH1	Stoup Side 1 to Steven Colbeck, Gloup 113111	Saved: 06 September 2001 09:	46
	PM called this morning - Advised her we need Access times	to swap the base unit.		
MODIFY	06 September 2001 09:47 by gb053549 / HSH1		Saved: 06 September 2001 09:	
Access Times	Call information modified by Steven Colbeck Call Type: from ' 06 September 2001 09:49 by gb053549 / HSH1	S to 'H' Prod. Descr.; to " Problem Type: from 'SD1	11' to 'HD15' Product Type: from 'P1 Saved: 06 September 2001 09:	
	Access Times: 0830 to 1730 Mon to fri.			
REASSIGN	06 September 2001 09:49 by gb053549 / HSH1		Saved: 06 September 2001 09:	•
	Call# E-0109051980 was Reassigned from Steven Colbeck, Passed the info on to MY STSA to change the number.	Group HSH1 to Group HSH5 Passing call across	- PO tel number is GRO	he number on the front screen is old office.
REASSIGN	06 September 2001 09:52 by GB082460 / HSH5		Saved: 06 September 2001 09:	52
	Call#E-0109051980 was Reassigned from Group HSH5 to 0	Group SMC1		
REASSIGN	06 September 2001 09:54 by uk066602 / SMC1 Call#E-0109051980 was Reassigned from Group SMC1 to \$	Pubasi Near Cray SMC1	Saved: 06 September 2001 09:	54
REASSIGN	06 September 2001 12:20 by GB082306 / SMC1	surface (Noor, Group Switch	Saved: 06 September 2001 12:	20
	Call # E-0109051960 was Reassigned from Suhael Noor, Gr	oup SMC1 to Group UKSS1		
REASSIGN	06 September 2001 12:53 by UK035161 / AUDIT1		Saved: 06 September 2001 12:	
Recommend	Call # E-0109051980 was Reassigned from Group UKSS1 to 06 September 2001 12:58 by uk082171 / SMC1	Group smc1 Please advise a recommendation as	s to what is required by the engine Saved: 06 September 2001 12:	
	Swap out gateway counter.			
Access Times	06 September 2001 12:59 by uk082171 / SMC1		Saved: 06 September 2001 12:	59
REASSIGN	Access Times: 0830 to 1730 Mon to fri. 06 September 2001 12:59 by uk082171 / SMC1		Saved: 06 September 2001 12:	50
TC-SOGN	Call#E-0109051980 was Reassigned from Group smc1 to G	Group UKSS1	Daves no deplember 2001 12.	
Information	06 September 2001 13:58 by uk083865 / UKSS2		Saved: 06 September 2001 13:	58
	Manual call logged due to OTi down ref. WB09060427			
Information	06 September 2001 14:01 by uk079674 / UKSS2 call assigned to Imran Rawat		Saved: 06 September 2001 143	01
REASSIGN	06 September 2001 14:01 by uk079674 / UKSS2		Saved: 06 September 2001 14:	01
	Call#E-0109051980 was Reassigned from Group UKSS1 to	Imran Rawat, Group UKSS1		
UPDATE	06 September 2001 14:45 by Dispatch 1 / Engineer 064008 despatched to site at 06-09-2001 14:46:00	** INo Remark entered.1	Saved: 06 September 2001 151	00
UPDATE	06 September 2001 15:23 by Dispatch 1 /	***************************************	Saved: 06 September 2001 15:	27
	Engineer 064008 arrived on site at 06-09-2001 15:24:00 ** [E	Engineer 064008 Logged On.]		
REASSIGN	06 September 2001 14:35 by Dispatch 1 / The projected arrival date for engineer 064008 is 06-09-200.	1.15.30:00 Enginger 064008 allegated	Saved: 06 September 2001 16:	00
UPDATE	06 September 2001 16:00 by Dispatch 1 /		Saved: 06 September 2001 16:	02
	Engineer 064008 arrived on site at 06-09-2001 15:24:00 I an	n waiting for smc to call me back due to a conf ig e		
UPDATE	06 September 2001 16:57 by Dispatch 17	4000 F	Saved: 06 September 2001 16:	59
UPDATE	I am waiting for smc to call me back due to a conf ig error at 06 September 2001 16:57 by Dispatch 1 /	20% 1090 I (Voli Installation result i s non-zero: 20	02 Saved: 06 September 2001 16:	59
	changed gateway processor due to software error.			T.T.
UPDATE	06 September 2001 16:58 by Dispatch 1 /		Saved: 06 September 2001 16:	59

EN LO VILOTE	22.0 2004 45.04 204000 (5) (5) (5)	0 1000 1 1 000110.57	
ENG VISIT	06 September 2001 15:24 by 064008 / ENGINEERS	Saved: 06 September 2001 16:57	
	changed gateway processor due to software error. Call closure code of failure and repair code 821		
REASSIGN	06 September 2001 16:59 by Dispatch 1 /	Saved: 06 September 2001:16:59	
	OTI monitor reassigned this call from Dispatch 1 to the Action Group UKSS2 as directed by the OTIReturn activity		
REASSIGN	06 September 2001 17:08 by uk080127 / UKSS2	Saved: 06 September 2001 17:08	
	Call # E-0109051980 was Reassigned from Group UKSS2 to Group HSH5		
REASSIGN	06 September 2001 17:08 by GB082460 / HSH5	Saved: 06 September 2001 17:09	
	Call # E-0109051980 was Reassigned from Group HSH5 to Group SMC1 For closure		
REASSIGN	06 September 2001 18:14 by uk081199 / SMC1	Saved: 06 September 2001 18:14	
	Call# E-0109051980 was Reassigned from Group SMC1 to Rebecca Aloneftis, Group SMC1		
CLEAR	06 September 2001 16:57 by uk081199 / SMC1	Saved: 06 September 2001 16:57	
	changed gateway processor due to software error. Call closure code of failure and repair code 821		
CLOSE	06 September 2001 18:17 by uk081199 / SMC1	Saved: 06 September 2001 18:17	
	Call Close by Rebecca Aloneftis: changed gateway processor due to software error. Call closure code of failure and repair code 821		