Message	
From:	Dunks Andy
Sent:	29/01/2010 14:31:37
To:	'john.longmar GRO
Subject: Attachments:	RE: WS for West Byfleet - Additional Information Requested WS West Byfleet 126023.doc
Take 2 !!	
how's this	?
Andy Dunks	
Security Te	am
•	Group Account .
Fujitsu Ser	vices Lovelace Road. Bracknell. Berkshire. RG12 8SN
;	
Tel: E-mail: and Web: http:/	GRO y.dunks GRO <mailto:victoria.hancock gro="" <br="">/uk.fujitsu.com <http: uk.fujitsu.com=""></http:></mailto:victoria.hancock>
3BW This e-mail privileged. is virus-fr	
Origin	al Message longmar
From: john.longmari GRO Sent: 29 January 2010 13:04 To: Dunks Andy Subject: Fw: WS for West Byfleet - Additional Information Requested	
Andy	
With regard	to question 3 below, can you confirm whether a list of exchanges has been received yet.
(Embedded i	mage moved to file: pic27921.jpg)
Forwarded by John Longmar GRO on 29/01/2010 13:02	
 	"Dunks Andy" GRO 15/12/2009 09:06
	To: <john.longman gro<="" td=""></john.longman>
	cc:
 	Subject: FW: FW: WS for West Byfleet - Additional Information Requested
>	

Please find below answers to the questions you asked. Can you confirm how you want the complete call information, do you want the whole call transferred to CD in it's raw state. There are over 100 of these..

Andy Dunks Security Team Royal Mail Group Account Fujitsu Services 4th Floor Lovelace Road Bracknell. Berkshire. RG12 8SN Tel: GRO E-mai Web: http://uk.fujitsu.com

Fujitsu Services Limited, Registered in England no 96056, Registered Office 22, Baker Street, London, W1U 3BW This e-mail is only for the use of its intended recipient. Its contents are confidential and may be privileged. Fujitsu does not guarantee that this e-mail has not been intercepted and amended or that it is virus-free

From: Machin Leighton Sent: 18 November 2009 12:08 To: Dunks Andy Cc: Lillywhite Tom; Thomas Penny

Subject: RE: FW: WS for West Byfleet - Additional Information Requested

Hi Andy,

Please find updates/answers to the questions below in red.

1) Please provide details of any business testing carried out by the Post Office on the system before it went live.

You would need to ask POL about this as we are only responsible for managing live service. Horizon has undergone stringent testing before it was installed and as far as I am aware, no evidence exists of the Horizon equipment ever being proven to have been responsible for anything untoward.

2) Please provide the service logs for the system at West Byfleet PO for a period commencing six months prior to the defendant taking over as sub postmistress (30/06/2005) to the present day. TfS was only installed in September 2007

3) Please confirm when and why the hardware in the system at West Byfleet PO has been changed. I have asked for a full list of exchanges carried out at this branch and will provide these details when I receive them.

4) By whom have these changes been made. These exchanges will have been completed by Touch logistics who are our preferred third party supplier for engineering services. They are purely hardware swaps following a standard set of processes.

5) When new hardware was installed at West Byfleet was it brand new or reconditioned All the Hardware is reconditioned, we will replace any hard-drives that show as having bad blocks at repair and we scrap any base units that are returned with the same fault three times. When kit is sent back from any branch, it has its memory wiped and a full software reload takes place. The install software is then installed, and the base unit is then uniquely configured to the FAD code it is being installed at when it is taken to site by the engineer. A base unit will NOT work at any branch if it is simply taken from one location and an attempted install is made at any other.

6) If it is the latter please confirm the identity of the PO from which the reconditioned hardware came and why the hardware has been removed from that PO.

The location of the hardware being installed at this branch is not relevant as is is returned to repairer prior to ever being sent out to a new branch and will undergo the tests and processes as described above.

Rgds Leighton

----Original Message----GRO From: john.longman Sent: 16 November 2009 14:11 To: Dunks Andy

Subject: RE: FW: WS for West Byfleet - Additional Information Requested

Andv

As per our telephone conversation of today I would be grateful if you could answer the following points raised by the defence.

- 1) Please provide details of any business testing carried out by the Post Office on the system before it went live.
- 2) Please provide the service logs for the system at West Byfleet PO for a period commencing six months prior to the defendant taking over as sub postmistress (30/06/2005) to the present day.

3) Please confirm when and why the hardware in the system at West Byfleet PO has been changed.

By whom have these changes been made.

5) When new hardware was installed at West Byfleet was it brand new or reconditioned

6) If it is the latter please confirm the identity of the PO from which the reconditioned hardware came and why the hardware has been removed from that PO.

(Embedded image moved to file: pic12074.jpg)

Royal Mail Group Limited registered in England and Wales registered number 4138203 registered office 3rd Floor, 100 Victoria Embankment, London, EC4Y OHQ

This email and any attachments are confidential and intended for the addressee only. If you are not the named recipient, you must not use, disclose, reproduce, copy or distribute the contents of this communication.

If you have received this in error, please contact the sender and then delete this email from your system.

Royal Mail Group Limited registered in England and Wales registered number 4138203 registered office 3rd Floor, 100 Victoria Embankment, London, EC4Y OHQ

This email and any attachments are confidential and intended for the addressee only. If you are not the named recipient, you must not use, disclose, reproduce, copy or distribute the contents of this communication.

If you have received this in error, please contact the sender and then delete this email from your system.
