1 8 NOV 1999

-2228.

Electronic memo



John Meagher/POCL/POSTOFFICE@POSTOFFICE

CC

Keith K Baines/POCL/POSTOFFICE@POSTOFFICE, min@marden.

GRO

Hard Copy To Hard Copy cc

From

Min Burdett/POCL/POSTOFFICE

Date

18/11/99 17:51

Subject

Papers for tomorrow

John

I attach:

Updated traffic light report:



November 24 Rollout stats6.doc

Updated Demand Paper:



Rollout Decision 2.doc

Background Paper (you'll need to make some changes as you get some info tomorrow):



Acceptance Meeting 22nd November 1999.doc

BSM reference data analysis which I don't understand but will look at to see if there's anything we should put in the background paper



Reference4.doc

Martin Box's stats updated with John Dick's view over the phone today:



Al3760.61.xls

You will also have two e-mails from Graeme Seedall - His to Keith Falconer this morning describing the issue and his reference data one sent this evening.

Give me a call on GRO tomorrow if you want some more info

Min

Roll-out 2000 Criteria - Monitoring Report

Version 0.6

Update for 22 Nov Checkpoint Meeting

	Week Commencing					21/10	28/10	4/11	11/11	Total	Red/Amber/ Green
AI 298/1	The number of system stability incidents for the four week period 21/10 to 17/11 shall be less than 560.					119	201.5	112.5	117.5	549	Green 💮
		24/9- 2/10	3/10- 6/10	7/10- 13/10	14/10- 20/10	21/10- 27/10	28/10- 3/11	4/11- 10/11	11/11- 14/11	Total/ Average	Red/Amber/ Green
AI 376/1	The percentage of cash accounts containing discrepancies shall not exceed 0.6%		44.92%	42.97%	32.04%	2.24%	0.90%	0.39%		15.97%	Red
AI 376/2	No cash account discrepancy will be as a result of a cause previously reported to POCL as having been remedied			0	0	0	0	0		0	Green
AI 376/3	All new causes of cash account will be analysed and have a rectification plan, submitted to POCL, within 10 days (Number without analysis/rectification plan)	5	1	7	2	4	1			20	Red
AI 376/4	The Accounting Integrity Control Release would have identified all new Cash Account Discrepancies reported prior to 24 th November (number not identified)									3	Red
AI 376/5	Those elements of the Rectification Plan for AI 376 which are scheduled to be complete by 24/11 shall be complete									On Track	Amber
	Week Commencing			4/10	11/10	18/10	25/10	1/11	8/11	Total/ Average	Red/Amber/ Green
AI 408/1	Service Levels for answering Level 1&2 calls to the Help Desk is met in at least four of the six weeks as follows: 95% of first level calls to be resolved in 5 minutes			97%	95%	96%	96%	96%	96%		Green O
b)	100% of first level calls to be resolved in 10 minutes			100%	100%	100%	100%	100%	100%		Green
c)	95% of second level calls to be resolved in 30 minutes			96%	100%	99%	99%	100%	100%		Green
d)	100% of second level calls to be resolved in 45 minutes			98%	100%	100%	100%	100%	100%		Green
AI 408/2	Service Levels for answering 80% of calls to the Help Desk within 20 seconds is met in at least four of the six weeks			69%	82%	82%	66%	72%	83%		Red
AI 408/3	Service Levels for cash account calls (no ring backs required) is met in at least four of the six weeks									Disputed data	Amber
AI 408/4	Service Levels for Cash Account repeat calls is met in at least four of the six weeks									Disputed data	Amber
AI 408/5	Service Levels for 95% compliance on Cash Account call scripts is met in at least four of the six weeks			N/A	40%	N/A	36%	70% 24%	N/A		
AI 408/6	The Contractor's Horizon System Helpdesk Service shall provide first, second and third level Services as described in Schedule G01									Agree	Green 💮

Roll-out Decision - Demand Position Paper

In anticipation of the criteria due to be met by 24th November not having been met by that date, and given POCL's associated concerns, POCL is proposing that the existing monitoring activities should continue and be strengthened, and is also proposing the introduction of some new activities. POCL proposes the following.

1. AI 298 - System Stability

Objective:

to ensure that Pathway continue to reduce the level of instability.

Activities:

- the current recording at the HSH does not facilitate the analysis and identification of faults
 and trends. POCL believe the best way of doing this is for Pathway, at their own expense,
 to develop a codified and structured fault recording system that will allow analysis to
 support the combined problem management and resolution function
- the current monitoring should continue for a further four weeks. The target for this period should be the same as the current period.

2. AI 376 - Data Integrity

Objectives:

- to ensure that the integrity control is capable of detecting all relevant incidents
- to continue to monitor error levels so POCL has an appropriate view of the level of disruption and cause of new incidents
- to increase POCL's level of understanding of the design and operation of emerging reconciliation controls:
 - a) to be in a position for POCL to design complementary operational procedures
 - b) obtain confidence that the new controls will be effective given the constrained level of testing, POCL require greater level of assurance before release into the live environment. This is necessary in order for POCL to be assured that criteria 376 iii and iv are being met

Activities:

- The EPOSS/TIP reconciliation feature must be proven to be capable of detecting all data
 errors that would be detected by the TIP cash account compare process; for the avoidance
 of doubt, this includes an explicit check that receipts are equal to payments. This to be
 achieved by:
 - · logical assurance of authorised design documentation
 - analysis of all previous root causes to determine that errors would be detected
 - testing to a jointly agreed strategy and high level test plan
 - dual running of EPOSS/TIP reconciliation and TIP Cash Account processes on test and live environments, over the periods described in CCN560, and subject to known stress conditions including outlet migration, reference data changes, transaction level data corruption
- the current monitoring should continue as defined in the second supplemental agreement for criteria 376 i-iii with the monitoring period commencing on the 18th November
- Pathway should demonstrate that they have met criterion 376 iv, if necessary by enhancing
 their Integrity Control design. This should include faults identified before September 24th
 and any faults found in the current monitoring period which would not have been detected
 by the current integrity control design
- Pathway should co-operate with POCL to review and revise the Rectification Plan to
 include new activities necessary for the successful development and implementation of
 operational procedures and any other new activities shown to be necessary by the review
- Pathway to extend the Logical Design information that is contractually controlled to cover those areas that POCL's experts reasonably say need to be subject to POCL's agreement, mainly interface and operational procedures

- mindful of the short time scales and the desire not to impede progress, the POCL ATM to be integrated into Pathway's delivery team so that POCL can gain the appropriate level of visibility in the design and progress to give POCL confidence in the Release
- Pathway's progress in developing the integrity release to be included in the scope of the review of readiness for roll-out which has been agreed and will be carried out by PA Consulting
- TIP checking shall continue at Pathway's expense until both of the following have occurred:
 - four weeks parallel running without faults as in the current contract
 - Pathway to have modified their integrity control to detect all error types that have occurred by that date.

3. AI 408 - HSH Performance

Objectives

- to give POCL confidence that HSH can support roll-out especially:
 - a) to ensure that the HSH is appropriately resourced for the peak periods within a week
 - b) to ensure conformance to scripts.

Activities

- continue to monitor HSH criteria i, iii and iv for a further four weeks. The six week
 monitoring period to be 1st November to 12th December. As per the original criteria, the
 aim being to attain the target levels in four out of the six weeks. In addition, 408 ii and v
 criteria should be enhanced (see below)
- to facilitate a detailed analysis of the root cause of the problems and allow POCL to have a
 more transparent understanding of ICL Pathway's performance, criterion 408 ii (calls
 answered within 20 seconds) should be reported during the four week extended period on
 a daily basis. The target of 80% of all calls answered within 20 seconds should be met
 every Wednesday and Thursday for three out of the four weeks and achieved as a weekly
 average for the same three out of the four weeks.
- to permit POCL to perform an audit of actual physical resource to the planned resource levels, Pathway to supply the four week detailed resourcing model broken down into 30 minute slots. POCL should be permitted to undertake an audit of physical resource to this model at any time during the 4 week period without prior notice. The actual resource levels should be within 95% of the planned levels for every audit performed
- paragraph 4.3.2.9 of schedule G10 (as amended by Schedule 5 of CCN560) to be further amended so that the compliance with the scripts shall be measured using call recordings which have been in operation since 1st November. A joint Pathway and POCL team to review and agree whether the operator has conformed to the scripts. The call logs detailing the scripts that have been used by the operator can be used as supporting evidence for the call recordings and can form part of the review to determine compliance. Pathway must achieve the target for the final three weeks of the audit. For this method of monitoring compliance to be effective:
 - a) Pathway to satisfy POCL that Pathway auditors have the expertise to undertake the review
 - b) POCL to select the calls at random
 - c) all cash account calls to be recorded.

Note that this also has the effect of changing the method of measuring criterion 408v

Pathway to continue to work with POCL to review the quality of script to improve the
accuracy leading to timely resolution of incidents. Additionally this will allow Pathway to
acquire business knowledge from POCL.

4. Reference Data

Objective

 to give POCL confidence that Pathway's service is robust and can accurately account for POCL's transactions during reference data changes

Activities:

- The Reference Data interface agreement must be re-introduced, agreed and brought under contract control.
- Pathway must analyse all possible reference data changes in relation their impact on the target application(s) and derive a set of rules which protects the applications from all unintended effects.
- A robust management process is defined, agreed and brought under contract control to enforce this set of rules.
- A "reference data proving" test environment is created and maintained within the Pathway domain, on which all reference data releases are subject to formal (jointly agreed) test.
- All recommendations emerging from the joint end-to-end reference data process review
 Tactical stage which relate directly to accounting integrity are implemented.
- In principle agreement is reached on the deliverables and costs for the joint end-to-end reference data process review: Strategic stage. To include as a minimum that ...
- The Pathway owned target applications are reviewed such that they are more resilient to reference data changes and less reliant on protection mechanisms expressed in the above rule set.
- The different approaches taken by the two organisations to accounting principles is reviewed and harmonised where deemed appropriate.

Acceptance Meeting 22nd November 1999

General Background Information

For the Acceptance meeting on 22nd November between POCL and Pathway to discuss the continuation of the roll-out in 2000, the following have been prepared:

- Negotiation Brief (Keith Baines)
- Demand Position Paper (John Meagher)
- General Background papers (various contributions).

The general background papers consist of:

- this paper containing descriptions of issues and justifications of POCL's position on the monitoring report
- Monitoring Report (traffic lights Min Burdett)
- Supporting data to the monitoring report
 - AI 298 graph report (DN awaiting final one)
 - AI 376 spread sheet analysis for each criterion
 - AI 408 Pathway's report
- paper for Keith Falconer describing the shortcomings and risks associated with the Integrity Control release (Graeme Seedall).

Status of Monitoring Report

AI 298
 There are on-going discussions with Pathway to finalise and agree the data.

2. AI 376

AI 376 - Giro reference data integrity problem (Graeme Seedall - DN awaiting draft)

AI 376/1. It should be noted that Pathway have re-classified the Root causes using their own taxonomy. These and the associated figures have been added to POCL's detailed AI376 monitoring report (see attached). Pathway may argue that only their category 4 (Cash Account Discrepancy (not reference data)) should be used in the monitoring statistics and therefore they have met the criterion.

AI 376/3. Pathway's view is that there are only 4 new causes of cash account discrepancies which have not been analysed and a rectification plan submitted in 10 days. We don't accept this view, and even if we did it would be a fail.

AI 376/4. Pathway's view is that there are no Cash Account discrepancies which would not have been identified by the Accounting Integrity Control Release. This is presumably be because they consider "Reversal of stock adjustment settlement", "negative giro records", and "Ecco transfer problem" as out of scope of this AI. Pathway will not provide any design documentation to confirm their analysis.

AI 376/5. Cycles 2 and 3 of System Testing will commence on 23rd November. This represents a slippage of eight calendar days against the original plan.

3. AI 408

AI 408/2. Pathway (John Dicks) are reporting this as passed as they are using 81% not 72% for the week beginning the 1st November. They are excluding calls due to reference data problems for this week. POCL do not agree with this exclusion.

AI 408/3 and 4. POCL are disputing the figures provided by Pathway which are generally no ring backs or repeat calls. POCL and Pathway are meeting Monday 22nd pm to try and resolve the difference of opinion (DN Adele Henderson should be providing on Friday POCL's view of the figures going into the meeting).

AI 408/5. Pathway are disputing POCL's audit approach which has been used. POCL agree. This criterion is therefore void.

AI 408 - issues with Reference Data (Dave McLauglin - DN analysis provided, but not sure what it's saying - probably delete this point)

Reference data problems

Area where	Problem	Problem Title	Action Taken	Status
		110blem 11tte	Action Taxen	Status
resolution lies	Number			
POCL Head	BSM19990916001	Special Promotion vouchers	Authorised Temporary Procedure (ATP)	ATP withdrawn
office	DSMITYYYOUT	(Bunches) were not accountable	implemented.	
OTTICE		on the Horizon System.	Ensure that all future instructions are checked	Closed
9		The account team did not follow	for Horizon compatibility before they are	
٠,		OBC procedures to change product.	released.	, ,
×	BSM19990916002	Software missing for Northern		Transaction now on the
	BSM19990916002	Ireland MVLs. Offices unable to		system. Offices are able
]		carry out transaction.	·	to carry out transaction.
*	ar.	The account team did not follow		Account team aware of
		OBC procedures to change		OBC procedure.
		product.		Closed
	BSM19991007001	£2 British Gas stamps not on the	Authorised Temporary Procedures (ATP)	Stamp icon now on the
	D2W119991007001	system.	implemented. Ensure that Account teams are	system. Awaiting
1	1	Product withdrawn and then	aware of the OBC procedures when changing or	Counter News article to
	* ,	reinstated to sell to exhaustion.	introducing new products.	inform users.
		Account team did not follow OBC		
		procedure.		
	BSM19991025005	Simple Payment Module Trial		Should be available on
	B5M19991025005	was extended and was not	1	the system by 3 Dec at
	,	available on the Horizon system.	* *	the earliest.
		Account team did not figure		3
. *	¥i	Horizon into their plans so sent		,
	, , , , , , , , , , , , , , , , , , , ,	no OBC form.		

Area where	Problem	Problem Title	Action Taken	Status
resolution lies	Number	*		
POCL Head office	BSM19991022002	SWALEC bar-coded bills not being recognised by the system	This is a client error as the problem is caused by the check digits in the bar-code not being recognised.	Short lived as only affected one batch of client bills.
	BSM19991105001	Lancashire homecare stamps not on the system. Migrated offices in this area could not put the new value stamps on the system. OBC not processed at OSG.	Authorised Temporary Procedure (ATP) implemented. Ensure account teams check that their OBC forms have been received by OSG	Awaiting conformation that stamps are on system
OSG	BSM19991105003	Users unable to find national savings Girobank transaction icons. Offices could not find these icons as they had been prematurely moved.	Explanations received from both ICL Pathway and OSG. OSG will tighten up their internal processes for verification and change to ensure no more misunderstandings.	Users informed. Awaiting update from OSG.
Reference data	BSM19991029003	Lack of adequate Reference Data Processes	There have been a number of problems raised which were due to reference data problems and a lack of management for the reference data process. There needs to be a complete review of how the business deals with reference data and the processes designed to manage reference data.	Ongoing
	BSM19990922001	Girobank Transcash fee set at 97p. Users could not alter the fee. Problem in Reference Data front end system.	Change request to RDS, which will stop future occurrences of this incident.	Awaiting conformation of change

Area where	Problem	Problem Title	Action Taken	Status
resolution lies	Number			ii ii
ICL Pathway	BSM19990922002	Corrupt Correspondence Server at Wigan	Technical explanation as to the cause has been given by ICL Pathway and agreed by Pathway	Post implementation review to be held.
	* .	The correspondence server at Wigan became corrupt and the system had to run off the Bootle	have given assurances that the underlying software bug has been dealt with and that this specific bug will not re-occur.	• 1
•		site however ICL Pathway		,
		informed BSM that the reference data for the previous evening	Products were sent to counter the following day.	
*		would not be run.	uay.	,
		12 products not available at counter.		
	BSM19990928002	Missing icons on the Horizon System (CO-OP banking)	ICL have released necessary Reference Data to re-instate the missing icon.	Icons back on system.
		Users could not find icon. to do transaction. Problem occurred within Icl Reference data.	Explanation received.	A
	BSM19991001001	Reference Data Scheduling - 1 Sided Transfers. Products could not be remmed or	A change has now been made to the operational procedures to include an additional level of consistency checking. This includes the	Ongoing. Residual incidents to be investigated.
	, ,	transferred out. e.g. cheques.		
	BSM19991013002	Discrepancies in the amount entered in Giro Change giving	An ICL Pathway CHANGE (NB this is not a fix) will be released to being this into line. This	Ongoing

Г			This showed when offices	change is currently with ICL Pathway testing, -	
	9		produced their cash account.	(WP 5711). The reference data change has not	4
1			•	given rise to any reconciliation occurrences	
ŀ			*	within the live ICL Pathway system, but has	
				within Interim TIP. When the ICL Pathway	
	*			change is released to the entire estate, this will	**
		* *	**	synchronise Interim TIP with the entire ICL	
		*		Pathway system.	
			Duplicate transaction numbers for	A fix was sent down in beginning of August	Call closure agreed by all
ľ		BSM19991028005	BA OBCS transactions.	and this was monitored. ICL are currently	parties.
		8	The BA reported to the BA	awaiting information from BA to see if the	. ,
	,	*	Account Team that they had had a	problem has reoccurred.	٠
			number of duplicate transaction	•	
	Ì		numbers for OBCS.		
			Girobank Business deposit	There appears to be a gap in the ICL pathway	Ongoing work to
ı		BSM19991105002	account number field missing.	testing of a product and OSGs verification.	establish gap.
			Users could not input the Giro	ATP issued to offices as transaction could be	
			account number.	accessed on another screen.	
	Ì	**	Caused by lack of full testing of	Problem rectified.	·
L			change.		·

Al 376 - Incident Analysis								,		
	Number of	outlets at	fected by	cash acco	unt week					
Root cause	Wk : 29-Sep : 27	6-Oct 28	13-Oct 29	3.4.1	27-Oct 31	3-Nov 32	10-Nov 33		Total	% in error
1 Negative sign on transactions						2		:	2	0.02%
2 Reversal of stock adjustment settlement	:	2	14	13		fix applied	THE WAY	进行数据法	29	0.36%
3 Incorrect stock transfer transactions		32	12				* .	:	44	0.54%
4 Missing cash account records	:		1		3			:	4	0.05%
5 Negative giro change records	: 2	367	424	388	5	ref data upd	ated 1	11.12.14.1	1186	14.59%
6 Invalid Item Transaction Mode	<u> </u>								0	0.00%
7 ECCO transfer problem		8		3					3	0.04%
8 AP reversal mode failure			3	1	1			:		0.00%
9 Outlet discrepancies under investigation		. 1	28	. 8	. 24	14	7	-	82	1.01%
Totals) (d. 1972	402	482		4.00 / 10/33	16	光点图集677 7	S18743 S105	1355	3,2113) (4)27
No.of outlets affected	2	385	452	404	33	15	. 7		1298	
No.of cash accounts received by POCL	24	857	1052	1261	1472	1675	1788		8129	
% of cash accounts in error (all root causes)	6.33%	44.92%	42.97%	32.04%	2.24%	0.90%	0.39%		15.97%	
% of cash accounts in error (excluding negative giro change)	0.00%	4.08%	5.51%	1.98%	1.90%	0.90%	0.39%		2.02%	
	ا : ا	observation p	eriod starts		l		L	obser	vation period ends	
Not an incident		1							1	,

Note:- Week 27 figures only include cash accounts received from 3/10

Pathway's View (given over 'phone to John Meagher/Min Burdett 18/11)					1.4	,				
1 POCL Reference Data		2 367	424	388	5	0	0		1186	14.59%
2 Other not 376 related (includes 2 of POCL's list)		0 2	15	18	6	4	0		45	0.55%
3 Pathway Reference Data		0 32	40	3	0	0	0		75	0.92%
4 Cash Account Discrepancy (not reference data)		0 1	3	1	22	0	0		27	0.33%
5 Under Investigation		0 0	0	3	2	11	7		23	0.28%
写了多数分类的思想是是对外的影响是是特别的形式的影響的是由于	SPARA	2 402	482	9 / 413	35	15	空间的混乱7	M/-HW///O	D 68 1356	16.68%

NB Pathway analysis does not take into account cash accounts affected by more than one root cause in a week